
## July 2016 Heat Testing

Testing took place at our Carlstadt, New Jersey location. On July 13th the temperature was 86° and on July 20th the temperature was 88°. Our products were tested in direct sunlight for duration of the day. This chart gives a range of temperatures for each product and finish.



Disclaimer: Applicable to Marmiro Stones® Products,

The following product and installation information is provided to assist Marmiro's customers with installation, maintenance and usage decisions. It is understood that the installation, maintenance and usage employed by each customer is outside the direction and control of Marmiro Stones\* and as such, is strictly and completely the choice and responsibility of each customer and their installer. Marmiro Stones\* expressly disclaims any and all asserted claims which may arise directly from information contained in this document(s), including but not limited to, loss of rights, materials, personal injury or other potential injury.